

GENERATING UNIT OUTAGES FOR THE WEEK

FROM 31-May-10 TO 6-Jun-10

UNIT UNDER PLANNED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reason
Cent_Sect	KARPR1	220	1-Jul-08	00:10		Continued.	COH(En-Mass Coolant Clanel Replacement)
Chandrapur	Unit 6	500	1-Apr-10	01.15		Continued.	Annual Overhaul
Chandrapur	Unit 1	210	8-Apr-10	08.36		Continued.	Annual Overhaul
Dabhol	2B	230	15-Apr-10	01.40		Continued.	Control System modification work
Chandrapur	Unit 5	500	16-Apr-10	15.49		Continued.	Water Balancing Problem.
Chandrapur	Unit 2	210	18-Apr-10	21.38		Continued.	Clinker Formation.
Chandrapur	Unit 7	500	25-Apr-10	00.23		Continued.	Water Balancing Problem.
Cent_Sect	NTPC(K-4)	500	9-May-10	07.00		Continued.	Annual Overhaul
Cent_Sect	NTPC(V-4)	210	19-May-10	17:09		Continued.	Annual O/H .
Chandrapur	Unit 3	210	26-May-10	23.59		Continued.	Water Balancing Problem.

UNIT UNDER FORCED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reason
Uran	Unit 2	60	4-Oct-08	19.00		Continued.	Gas Restriction
Uran	Unit 4	60	1-Apr-09	00:00		Continued.	Gas Restriction
Parli	Unit 7	250	28-May-10	21.41	7-Jun-10	14.00	Low Pressure bypass valve leakage
Koradi	Unit 7	210	30-May-10	11.22	31-May-10	06.39	Furnace Pressure High.
Cent_Sect	NTPC(K-5)	500	30-May-10	14.45	31-May-10	21.39	Boiler Tube Leakage
Tata	Trombay 5	500	31-May-10	13.32	31-May-10	17.56	Aus.Supply Failed.
Cent_Sect	NTPC(K-6)	500	31-May-10	15.37	2-Jun-10	03.59	Cooling water pump problem.
Nasik	Unit 2	120	1-Jun-10	11.10	5-Jun-10	11.20	BLR T/L
Khaparkhedda	Unit 1	210	1-Jun-10	16.23	1-Jun-10	23.01	W/Dn,as B-Ph CT jumper broken.
Cent_Sect	Sipat-4	500	2-Jun-10	13.08	5-Jun-10	03.23	BLR T/L.
Koradi	Unit 4	105	3-Jun-10	11.09	4-Jun-10	08.54	Coal Problem
Koradi	Unit 6	210	3-Jun-10	20.06	5-Jun-10	08.56	High Furnance Pressure
Khaparkhedda	Unit 4	210	4-Jun-10	13.42	4-Jun-10	18.42	HPT Control valve problem.
Uran	Unit 5	108	4-Jun-10	17.05	4-Jun-10	18.25	Flame Failure
Uran	Unit 5	108	4-Jun-10	18.57	4-Jun-10	20.08	Boiler problem.
Uran	Unit 5	108	4-Jun-10	23.12	5-Jun-10	00.51	CTO High
Koradi	Unit 7	210	5-Jun-10	04.57	5-Jun-10	09.04	Furnance Pressure High
Nasik	Unit 4	210	5-Jun-10	13.50		Continued.	ID Fan Problem
Bhusawal	Unit 1	58	5-Jun-10	11.30	6-Jun-10	01.10	Flashover primary Air Fan
Paras	Unit 4	250	5-Jun-10	12.35	5-Jun-10	18.52	Flame Failure
Bhusawal	Unit 1	58	6-Jun-10	01.20		Continued.	Suspected rear water wall leakage
Uran	Unit 7	108	6-Jun-10	03.09	6-Jun-10	06.32	Generator Protection
Uran	Unit B0	120	6-Jun-10	07.57	6-Jun-10	10.44	Boiler Protection
Uran	Unit 8	108	6-Jun-10	07.57	6-Jun-10	08.34	Boiler Protection