

GENERATING UNIT OUTAGES FOR THE PERIOD

FROM 30-Aug-10 TO 5-Sep-10

UNIT UNDER PLANNED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reason
Cent_Sect	KARPR1	220	1-Jul-08	00:10		Continued.	COH(En-Mass Coolant Clanel Replacement)
Koyna	ST-IV 1	250	16-Jul-10	00.00		Continued.	Preparing Work for 2nd Lake Tapping.
Koyna	ST-IV 2	250	16-Jul-10	00.00		Continued.	Preparing Work for 2nd Lake Tapping.
Koyna	ST - IV 3	250	16-Jul-10	00.00		Continued.	Preparing Work for 2nd Lake Tapping.
Koyna	ST - IV 4	250	16-Jul-10	00.00		Continued.	Preparing Work for 2nd Lake Tapping.
Bhusawal	Unit 3	210	31-Jul-10	05.26	3-Sep-10	19.40	Annual Overhaul.
Cent_Sect	KARPR2	220	14-Aug-10	14:16		Continued.	Annual Overhaul.
Koradi	Unit 4	105	24-Aug-10	06.02		Continued.	Annual Overhaul.
Khaparkheda	Unit 2	210	27-Aug-10	23.40		Continued.	Capital Overhaul
Cent_Sect	NTPC(V-8)	500	20-Aug-10	00.46		Continued.	Annual Overhaul
Khaparkheda	Unit 2	210	27-Aug-10	23.40		Continued.	Capital Overhaul
Cent_Sect	NTPC(V-8)	500	20-Aug-10	00.46		Continued.	Annual Overhaul

UNIT UNDER FORCED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reason
Uran	Unit 2	60	4-Oct-08	19.00		Continued.	Gas Restriction
Uran	Unit 4	60	1-Apr-09	00:00		Continued.	Gas Restriction
Uran	Unit 3	60	16-Jun-10	19.52		Continued.	R.M.Work.
Parli	Unit 1	30	18-Jun-10	12:11		Continued.	For Scrapping.
Dabhol	2A	230	12-Jul-10	01.55		Continued.	Tripped due to Electrical Fault
Koradi	Unit 1	105	25-Aug-10	11.51		Continued.	Boiler Inspection.
Nasik	Unit 3	210	27-Aug-10	07.50	31-Aug-10	04.38	Boiler tube leakage.
Bhusawal	Unit 1	58	27-Aug-10	19.40	30-Aug-10	13.30	Wet coal problem.
Koradi	Unit 5	200	28-Aug-10	00.57	30-Aug-10	00.39	Boiler tube leakage.
Chandrapur	Unit 4	210	28-Aug-10	19:43	4-Sep-10	07.18	Tripped on Differential Expansion.
Khaparkheda	Unit 4	210	28-Aug-10	23.18	4-Sep-10	22.17	Heavy seal oil leakage of Generator
Paras	Unit 4	250	29-Aug-10	20.20	31-Aug-10	16.47	Flame failure.
Dabhol	2B	230	30-Aug-10	11.32	1-Sep-10	01.44	Gas Leakage.
Dabhol	2X	290	30-Aug-10	11.32	1-Sep-10	03.23	Gas Leakage.
Parli	Unit 3	210	30-Aug-10	11.56	30-Aug-10	20.37	Furnace Pressure High.
Chandrapur	Unit 3	210	30-Aug-10	17.28	30-Aug-10	21.20	Furnace Pressure High.
Parli	Unit 4	210	30-Aug-10	06.35	31-Aug-10	22.15	L P T Diff.Expansion High.

Chandrapur	Unit 3	210	30-Aug-10	22.17	31-Aug-10	01.17	Trip.During Changeover of Aux.Supply.
Chandrapur	Unit 3	210	31-Aug-10	04.30	31-Aug-10	06.30	Vaccume Pressure Low.
Nasik	Unit 3	210	31-Aug-10	04.50	31-Aug-10	06.10	Due to Boiler Tripping.
Nasik	Unit 1	120	30-Aug-10	21.50	31-Aug-10	11.30	Coal Problem.
Nasik	Unit 1	120	31-Aug-10	14.30	3-Sep-10	17.00	Steam Temp.Low.
Nasik	Unit 4	210	31-Aug-10	11.26	2-Sep-10	08.05	Wet Coal.
Chandrapur	Unit 3	210	31-Aug-10	08.05	5-Sep-10	05.27	Furnace Pressure High.
Paras	Unit 4	250	31-Aug-10	19.15	31-Aug-10	21.04	Flame Failure.
Paras	Unit 4	250	31-Aug-10	22.17	1-Sep-10	01.24	M S Steam Temp.Low.
Koradi	Unit 5	200	1-Sep-10	04.20	1-Sep-10	08.03	Furance Pressure Drop.
Koradi	Unit 6	210	1-Sep-10	19.17	4-Sep-10	11.38	Coal Mill Chokeup
Parli	Unit 3	210	1-Sep-10	21.41	5-Sep-10	12.05	ESP Field Problem
Parli	Unit 7	250	2-Sep-10	00.34	2-Sep-10	05.34	PA Fan Problem
Bhusawal	Unit 1	58	1-Sep-10	23.30		Continued.	Wet Coal
Bhusawal	Unit 2	210	2-Sep-10	13.20	2-Sep-10	15.38	Furnace prot.operated.
Parli	Unit 7	250	2-Sep-10	08.53	3-Sep-10	06.46	Furnace pressure high.
Tata	Trombay 8	250	2-Sep-10	09.59	2-Sep-10	13.28	Master fuel trip.
Paras	Unit 2	55	3-Sep-10	05.05	3-Sep-10	07.05	Reverse power port.operated.
Uran	Unit 5	108	4-Sep-10	00.05	4-Sep-10	23.32	Filter replacement.
Paras	Unit 3	250	4-Sep-10	00.06		Continued.	CHP Belt replacement.
Paras	Unit 4	250	4-Sep-10	03.38		Continued.	Bunkering problem.
Cent_Sect	Gandhar U3	144	4-Sep-10	00.09		Continued.	Low demand.
Chandrapur	Unit 4	210	4-Sep-10	09.04		Continued.	Tripped due to axial shift very high.
Bhusawal	Unit 3	210	4-Sep-10	15.48	4-Sep-10	20.03	Loss of fuel.
Parli	Unit 7	250	4-Sep-10	13.31	5-Sep-10	01.17	Main steam temp.low.
Cent_Sect	NTPC(V-3)	210	4-Sep-10	12.00	5-Sep-10	21.38	Boiler tube leakage.
Parli	Unit 7	250	5-Sep-10	06.32		Continued.	Steam Temp.low.
Bhusawal	Unit 3	210	5-Sep-10	08.55		Continued.	Coal Mill Problem.
Chandrapur	Unit 3	210	5-Sep-10	17.11	5-Sep-10	22.03	Loss of Fuel.
Cent_Sect	NTPC(K-6)	500	5-Sep-10	23.50		Continued.	Boiler tube leakage.
Cent_Sect	Kawas GT2A	106	3-Sep-10	20.14		Continued.	Less Requisition
Parli	Unit 2	30	3-Sep-10	14.10		Continued.	BLR T/L.