

GENERATING UNIT OUTAGES FOR THE WEEK

FROM 7-Jun-10 TO 13-Jun-10

UNIT UNDER PLANNED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reason
Cent_Sect	KARPR1	220	1-Jul-08	00:10		Continued.	COH(En-Mass Coolant Clanel Replacement)
Chandrapur	Unit 6	500	1-Apr-10	01.15		Continued.	Annual Overhaul
Chandrapur	Unit 1	210	8-Apr-10	08.36		Continued.	Annual Overhaul
Dabhol	2B	230	15-Apr-10	01.40		Continued.	Control System modification work
Chandrapur	Unit 5	500	16-Apr-10	15.49		Continued.	Water Balancing Problem.
Chandrapur	Unit 2	210	18-Apr-10	21.38		Continued.	Clinker Formation.
Chandrapur	Unit 7	500	25-Apr-10	00.23		Continued.	Water Balancing Problem.
Cent_Sect	NTPC(K-4)	500	9-May-10	07.00		Continued.	Annual Overhaul
Cent_Sect	NTPC(V-4)	210	19-May-10	17:09	9-Jun-10	11.45	Annual O/H .
Chandrapur	Unit 3	210	26-May-10	23.59		Continued.	Water Balancing Problem.
Koyna	ST - IV 3	250	11-Jun-10	08.00		Continued.	Maintenance work
Koyna	Unit 1	75	13-Jun-10	06.30	13-Jun-10	18.25	Civil Work,Repair of Pot Whole Dimension Side W
Koyna	Unit 2	75	13-Jun-10	07.00	13-Jun-10	18.30	Civil Work,Repair of Pot Whole Dimension Side W
Koyna	Unit 3	75	13-Jun-10	07.05	13-Jun-10	19.00	Civil Work, Repair of Pot Whole Dimension Side W
Koyna	Unit 4	75	13-Jun-10	06.25	13-Jun-10	20.00	Civil Work,Repair of Pot Whole Dimension Side W
Koyna	Unit 5	80	13-Jun-10	06.10	13-Jun-10	19.05	Civil Work, Repair of Pot Whole Dimension Side W
Koyna	Unit 6	75	13-Jun-10	06.15	13-Jun-10	20.30	Civil Work,Repair of Pot Whole Dimension Side W
Koyna	Unit 7	80	13-Jun-10	06.40	13-Jun-10	19.15	Civil Work,Repair of Pot Whole Dimension Side W
Koyna	Unit 8	80	13-Jun-10	06.20	13-Jun-10	19.55	Civil Work,Repaire of Pot Whole Dimension Side W

UNIT UNDER FORCED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reason
Uran	Unit 2	60	4-Oct-08	19.00		Continued.	Gas Restriction
Uran	Unit 4	60	1-Apr-09	00:00		Continued.	Gas Restriction
Parli	Unit 7	250	28-May-10	21.41	7-Jun-10	14.00	Low Pressure bypass valve leakage
Nasik	Unit 4	210	5-Jun-10	13.50	11-Jun-10	18.15	ID Fan Problem
Bhusawal	Unit 1	58	6-Jun-10	01.20	8-Jun-10	01.50	Suspected rear water wall leakage
Koradi	Unit 5	200	7-Jun-10	10.02	8-Jun-10	15.10	I D Fan Problem.
Uran	Unit 3	60	7-Jun-10	19.14	7-Jun-10	21.47	Trip.
Parli	Unit 7	250	7-Jun-10	15.22	7-Jun-10	19.50	Main Steam Temp.Low.
Dabhol	1B	230	7-Jun-10	23.28	9-Jun-10	04.10	W/D For Attending Hot Air Leakage.
Koradi	Unit 4	105	8-Jun-10	07.06	9-Jun-10	14.45	Poor Bunkring.
Nasik	Unit 1	120	9-Jun-10	03.11	12-Jun-10	01.00	Boiler Tube Leakage.
Koradi	Unit 2	105	9-Jun-10	09.06		Continued.	Wind box red hot.
Uran	Unit 5	108	9-Jun-10	11.15	9-Jun-10	13.54	Gen.X'mer B Ph.burning clamp bolt replacement.
Koradi	Unit 4	105	9-Jun-10	16.44	10-Jun-10	20.21	Coal bunkering problem.
Parli	Unit 6	250	9-Jun-10	17.24	11-Jun-10	21.15	Boiler Tube Leakage.
Cent_Sect	NTPC(V-10)	500	9-Jun-10	08.55	9-Jun-10	21.47	Boiler Tube Leakage.
Cent_Sect	sipat-5	500	9-Jun-10	21.28	11-Jun-10	05.07	Boiler Tube Leakage.
Uran	Unit 8	108	10-Jun-10	00.47	10-Jun-10	16.38	Filter replacement.
Koradi	Unit 7	210	10-Jun-10	11.50	10-Jun-10	21.34	Bunkering problem
Khaparkheda	Unit 2	210	10-Jun-10	12.16	12-Jun-10	20.32	Boiler Tube Leakage
Cent_Sect	NTPC(V-10)	500	10-Jun-10	10.35	13-Jun-10	08.38	Boiler Tube Leakage
Koradi	Unit 7	210	10-Jun-10	23.08	11-Jun-10	02.58	Bunkering Problem
Koradi	Unit 5	200	11-Jun-10	04.42	13-Jun-10	21.20	ID Fan Problem
Parli	Unit 7	250	11-Jun-10	05.47	11-Jun-10	10.15	Furnance Pressure High
Uran	Unit 3	60	12-Jun-10	00.30	12-Jun-10	07.24	Gas Restriction
Koyna	Unit 5	80	12-Jun-10	01.55	12-Jun-10	17.50	Generator Aircooler leakage
Parli	Unit 6	250	12-Jun-10	20.02	12-Jun-10	23.00	Flame failure.
Parli	Unit 1	30	12-Jun-10	21.10	13-Jun-10	20.43	Bottom ash problem.
Bhusawal	Unit 2	210	12-Jun-10	14.03		Continued.	ID Fan problem.
Nasik	Unit 4	210	13-Jun-10	08.27		Continued.	Water Value Tube Leakage.
Khaparkheda	Unit 1	210	13-Jun-10	15.14	13-Jun-10	20.18	Falme Failure.