

GENERATING UNIT OUTAGES FOR THE PERIOD

FROM 12-Jul-10 TO 18-Jul-10

UNIT UNDER PLANNED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reason
Cent_Sect	KARPR1	220	1-Jul-08	00:10		Continued.	COH(En-Mass Coolant Clanel Replacement)
Chandrapur	Unit 5	500	16-Apr-10	15.49	17-Jul-10	20.17	Water Balancing Problem.
Chandrapur	Unit 3	210	26-May-10	23.59		Continued.	Water Balancing Problem.
Koradi	Unit 5	200	26-Jun-10	02:33		Continued.	Annual Overhaul.
Cent_Sect	NTPC (K-2)	210	30-Jun-10	23.46		Continued.	Annual Overhaul.
Cent_Sect	NTPC(V) 9	500	1-Jul-10	00.04		Continued.	Annual Overhaul.
Cent_Sect	Kawas ST2C	116	1-Jul-10	00.08		Continued.	Annual Overhaul.
Parli	Unit 4	210	5-Jul-10	09.27		Continued.	Capital Overhaul
Koyna	ST-IV 1	250	16-Jul-10	00.00		Continued.	Preparing work for 2nd lake tapping.
Koyna	ST-IV 2	250	16-Jul-10	00.00		Continued.	preparing work for 2nd lake tapping.
Koyna	ST - IV 3	250	16-Jul-10	00.00		Continued.	Preparing work for 2nd lake tapping.
Koyna	ST - IV 4	250	16-Jul-10	00.00		Continued.	preparing work for 2nd lake tapping.

UNIT UNDER FORCED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reason
Uran	Unit 2	60	4-Oct-08	19.00		Continued.	Gas Restriction
Uran	Unit 4	60	1-Apr-09	00:00		Continued.	Gas Restriction
Paras	Unit 2	55	13-Jun-10	17.35		Continued.	For Scrapping.
Uran	Unit 3	60	16-Jun-10	19.52		Continued.	R.M.Work.
Tata	Trombay 4	150	18-Jun-10	01.40		Continued.	Low demand.
Dabhol	1B	230	18-Jun-10	13.09		Continued.	Unit Differential.
Dabhol	1A	230	18-Jun-10	13.09		Continued.	Unit Differential.
Dabhol	1X	290	18-Jun-10	13.09		Continued.	Unit Differential.
Bhusawal	Unit 1	58	18-Jun-10	05:10		Continued.	For Scrapping.
Parli	Unit 2	30	18-Jun-10	06:26		Continued.	For Scrapping.
Parli	Unit 1	30	18-Jun-10	12:11		Continued.	For Scrapping.
Koradi	Unit 1	105	28-Jun-10	05.53	16-Jul-10	14.43	Low Bunkering.
Cent_Sect	TARAPUR-4	540	28-Jun-10	05.54		Continued.	System Deficiency.
Koradi	Unit 4	105	6-Jul-10	10.03		Continued.	Boiler Tube Leakage.
Parli	Unit 7	250	6-Jul-10	23.03		Continued.	Generator Protection Operated.
Koradi	Unit 2	105	9-Jul-10	07.46	19-Jul-10	09.42	Boiler Tube Leakage.
Koradi	Unit 3	105	10-Jul-10	01.15	17-Jul-10	10.31	Bunkering Problem.
Paras	Unit 4	250	11-Jul-10	19.48	12-Jul-10	12.31	Bunkering Problem
Dabhol	2A	230	12-Jul-10	01.55		Continued.	Tripped due to Electrical Fault
Dabhol	2B	230	12-Jul-10	01.55		Continued.	Tripped due to Electrical Fault
Dabhol	2X	290	12-Jul-10	01.55		Continued.	Tripped due to Electrical Fault
Nasik	Unit 4	210	12-Jul-10	04.35	12-Jul-10	16.00	Bunkering Problem
Nasik	Unit 5	210	12-Jul-10	05.05	12-Jul-10	15.10	Furnance Pressure inadequate
Cent_Sect	Sipat-4	500	12-Jul-10	10.38	14-Jul-10	05.26	Boiler Tube Leakage
Cent_Sect	TARAPUR-3	540	13-Jul-10	06.19		Continued.	Reactor Problem.
Paras	Unit 4	250	13-Jul-10	23.05	14-Jul-10	01:42	Loss of Fuel.
Cent_Sect	NTPC(V-2)	210	13-Jul-10	17.32	15-Jul-10	21.37	Boiler Tube Leakage
Paras	Unit 3	250	14-Jul-10	00.16	14-Jul-10	04.49	Drum level low.
Parli	Unit 3	210	14-Jul-10	20:35	15-Jul-10	03:49	Furnace Pressure High

Paras	Unit 4	250	15-Jul-10	19.27	15-Jul-10	21.25	Turbine Temp.High.
Tata	Trombay 7A	120	15-Jul-10	22.56	17-Jul-10	15.27	Turbine Protection.
Tata	Trombay 7B	60	15-Jul-10	22.56	17-Jul-10	23.17	Turbine Protection.
Parli	Unit 3	210	16-Jul-10	11.00	16-Jul-10	17.07	Furnance Pressure High
Nasik	Unit 2	120	16-Jul-10	19.35	18-Jul-10	07.45	Boiler Tube Leakage
Bhusawal	Unit 2	210	17-Jul-10	04.01	17-Jul-10	15.43	Coal Mill Problem
Koradi	Unit 7	210	17-Jul-10	06.44	19-Jul-10	15.37	Boiler Tube Leakage
Khaparkheda	Unit 2	210	17-Jul-10	10.05	17-Jul-10	10.30	Flame Failure
Paras	Unit 4	250	17-Jul-10	12.56	17-Jul-10	15.21	Low Drum Level
Nasik	Unit 5	210	17-Jul-10	21.55	18-Jul-10	00.15	Flashover in AC supply Board
Cent_Sect	sipat-5	500	17-Jul-10	21.17	19-Jul-10	03.20	Boiler Tube Leakage
Nasik	Unit 1	120	26-Jul-10	10.30		Continued.	Boiler Tube Leakage.
Bhusawal	Unit 2	210	27-Jul-10	12.56		Continued.	Boiler Tube Leakage.
Bhusawal	Unit 1	58	28-Jul-10	03.45		Continued.	Trip.
Koradi	Unit 2	105	28-Jul-10	11.31		Continued.	Bunkering Problem.
Bhusawal	Unit 2	210	12-Jun-10	14.03	15-Jun-10	00.57	ID Fan problem.
Nasik	Unit 4	210	13-Jun-10	08.27	14-Jun-10	23.29	Water Value Tube Leakage.
Khaparkheda	Unit 1	210	13-Jun-10	15.14	13-Jun-10	20.18	Falme Failure.
Paras	Unit 2	55	13-Jun-10	17.35		Continued.	For Scrapping.
Koradi	Unit 6	210	14-Jun-10	15.20	18-Jun-10	15.07	I D Fan Problem.
Koradi	Unit 4	105	14-Jun-10	22.57	16-Jun-10	21.32	Boiler Tube Leakage.
Bhusawal	Unit 2	210	15-Jun-10	08.55	18-Jun-10	22.04	BLR T/L.
Uran	Unit 3	60	15-Jun-10	12.10	16-Jun-10	07.55	W/Dn.
Dabhol	2A	230	15-Jun-10	08.59	15-Jun-10	14.39	Electrical fault.
Dabhol	2X	290	15-Jun-10	08.59	15-Jun-10	15.35	W/Dn.
Dabhol	2A	230	17-Jun-10	11.52	17-Jun-10	15.13	Tie breaker R Ph.burst.
Paras	Unit 4	250	15-Jun-10	20.55	30-Jun-10	03.13	Clinker Formation.
Nasik	Unit 4	210	15-Jun-10	22.42	16-Jun-10	01.25	Repl.of Turbine Trip Solenoid Coil.
Tata	Trombay 7B	60	16-Jun-10	08.52	16-Jun-10	19.11	Turbine pressure high.
Tata	Trombay 7B	60	16-Jun-10	19.36	17-Jun-10	07.18	Turbine pressure high.
Uran	Unit 3	60	16-Jun-10	19.52		Continued.	R.M.Work.
Koradi	Unit 4	105	16-Jun-10	24.00	17-Jun-10	09.04	Compressor discharge line probelm.
Nasik	Unit 1	120	17-Jun-10	03.05	18-Jun-10	23.40	Boiler Tube Leakage.
Khaparkheda	Unit 4	210	15-Jun-10	17.16	17-Jun-10	19.38	Boiler Tube Leakage.
Tata	Trombay 4	150	18-Jun-10	01.40		Continued.	Low demand.
Uran	Unit B0	120	17-Jun-10	12.03	17-Jun-10	14.05	Generator prot. trip,
Uran	Unit 7	108	17-Jun-10	12.05	17-Jun-10	12.44	Trip.
Uran	Unit 8	108	17-Jun-10	12.04	17-Jun-10	12.22	Trip.
Dabhol	2X	290	17-Jun-10	11.32	17-Jun-10	22.02	Tie breaker R Ph.burst.
Bhusawal	Unit 1	58	18-Jun-10	05.10	18-Jun-10	05:11	For scrapping.
Parli	Unit 5	210	18-Jun-10	16.50	18-Jun-10	21.00	Load variation.
Parli	Unit 2	30	18-Jun-10	06.26	18-Jun-10	06:27	For Scrapping.
Bhusawal	Unit 3	210	19-Jun-10	12.41	22-Jun-10	03.50	Boiler Tube Leakage
Parli	Unit 1	30	18-Jun-10	12.11	18-Jun-10	12:12	For scrapping.
Dabhol	1B	230	18-Jun-10	13.09		Continued.	Unit Differential.
Dabhol	1A	230	18-Jun-10	13.09		Continued.	Unit Differential.
Dabhol	1X	290	18-Jun-10	13.09		Continued.	Unit Differential.
Parli	Unit 5	210	19-Jun-10	12.10	19-Jun-10	16.53	Furnance pressure high
Nasik	Unit 5	210	19-Jun-10	18.50	19-Jun-10	21.10	Loss of Fuel
Koradi	Unit 2	105	19-Jun-10	14.35	19-Jun-10	21.32	Tripped on Mal Functioning of over Frequency

Tata	Trombay 8	250	19-Jun-10	08.27	19-Jun-10	14.14	Loss of Fuel
Koradi	Unit 2	105	20-Jun-10	08.06	23-Jun-10	22.48	Coal Problem.
Parli	Unit 6	250	20-Jun-10	02.25	20-Jun-10	06.27	ID Fan Problem.
Koradi	Unit 4	105	20-Jun-10	18.44	27-Jun-10	18.17	Boiler Tube Leakage.
Koradi	Unit 5	200	21-Jun-10	11.17	24-Jun-10	00.39	Bunkering Problem.
Parli	Unit 6	250	21-Jun-10	15.10	21-Jun-10	19.05	Furnace Pressure High.
Khaparkheda	Unit 3	210	21-Jun-10	15.22	21-Jun-10	22.10	Flame Failure.
Nasik	Unit 3	210	21-Jun-10	22.05	27-Jun-10	08.45	Boiler Hopper Leakage.
Uran	Unit 7	108	22-Jun-10	00.35	23-Jun-10	10.20	Filter Replacement.
Parli	Unit 5	210	23-Jun-10	02.44	23-Jun-10	08.21	Drum level very high.
Tata	Trombay 8	250	23-Jun-10	01.15	23-Jun-10	04.50	Header pressure low.
Parli	Unit 5	210	23-Jun-10	08.37	23-Jun-10	13.45	Drum level low.
Koyna	ST - IV 4	250	23-Jun-10	07.50	1-Jul-10	18.14	Servomotor seal replacement.
Parli	Unit 7	250	24-Jun-10	14.18	24-Jun-10	19.00	Steam problem.
Khaparkheda	Unit 2	210	24-Jun-10	19.50	24-Jun-10	23.00	Flame failure.
Parli	Unit 4	210	24-Jun-10	23.18	5-Jul-10	09.27	HPCV problem.
Paras	Unit 3	250	25-Jun-10	02.26	25-Jun-10	04.21	Clinker problem.
Uran	Unit 6	108	25-Jun-10	04.45	25-Jun-10	09.25	Rectifire fault
Chandrapur	Unit 2	210	25-Jun-10	21.25	26-Jun-10	01.34	Tripped due to failure of Stn Supply
REL	2	250	26-Jun-10	02.19	28-Jun-10	15.56	Condensor Tube Leakage
Dabhol	3A	230	27-Jun-10	00.20	29-Jun-10	00.40	Heavy Leakages in Boiler
Dabhol	2B	230	26-Jun-10	06.48	26-Jun-10	20.14	PPM trial
Parli	Unit 7	250	26-Jun-10	19.07	26-Jun-10	21.18	Tripped due to Turbine tripped
Chandrapur	Unit 1	210	27-Jun-10	10.10	27-Jun-10	12:45	Main Steam Temp.Low.
Koradi	Unit 6	210	27-Jun-10	13.53	28-Jun-10	19.13	Furnace Pressure High.
Paras	Unit 3	250	28-Jun-10	00:17	28-Jun-10	03.36	Drum level low.
Cent_Sect	NTPC(K-4)	500	27-Jun-10	18:57	29-Jun-10	06.58	Boiler Tube Leakage.
Dabhol	2A	230	28-Jun-10	02.39	28-Jun-10	06.40	U.A.Tr.Tripped.
Koradi	Unit 1	105	28-Jun-10	05.53		Continued.	Low Bunkering.
Cent_Sect	TARAPUR-4	540	28-Jun-10	05.54		Continued.	System Deficiency.
Bhusawal	Unit 2	210	29-Jun-10	13.31	29-Jun-10	15.25	Drum Level Low.
Parli	Unit 7	250	29-Jun-10	09.00	29-Jun-10	13.56	Low Drem Level.
Parli	Unit 7	250	29-Jun-10	19.50	30-Jun-10	00.28	Flame Failure.
Koradi	Unit 4	105	29-Jun-10	16.44	1-Jul-10	02.10	Bunkering Problem.
Chandrapur	Unit 2	210	30-Jun-10	11.48	30-Jun-10	13.46	Tripped during changing over of UAT supply.
Koradi	Unit 2	105	30-Jun-10	20.16	4-Jul-10	15.17	Boiler Tube Leakage.
Parli	Unit 7	250	30-Jun-10	19.09	1-Jul-10	02.04	Tripped on Main Steam Temp. Low.
Bhusawal	Unit 1	58	18-Jun-10	05:10		Continued.	For Scrapping.
Parli	Unit 2	30	18-Jun-10	06:26		Continued.	For Scrapping.
Parli	Unit 1	30	18-Jun-10	12:11		Continued.	For Scrapping.
Koradi	Unit 4	105	6-Jul-10	10.03		Continued.	Boiler Tube Leakage.
Parli	Unit 7	250	6-Jul-10	23.03		Continued.	Generator Protection Operated.
Koradi	Unit 2	105	9-Jul-10	07.46		Continued.	Boiler Tube Leakage.
Koradi	Unit 3	105	10-Jul-10	01.15		Continued.	Bunkering Problem.
Paras	Unit 4	250	11-Jul-10	19.48		Continued.	Bunkering problem
Dabhol	2A	230	12-Jul-10	01.55		Continued.	Tripped due to Electrical Fault
Dabhol	2B	230	12-Jul-10	01.55		Continued.	Tripped due to Electrical Fault
Dabhol	2X	290	12-Jul-10	01.55		Continued.	Tripped due to Electrical Fault
Nasik	Unit 4	210	12-Jul-10	04.35		Continued.	Bunkering Problem
Nasik	Unit 5	210	12-Jul-10	05.05		Continued.	Furnance Pressure inadequate