

GENERATING UNIT OUTAGES FOR THE PERIOD

FROM 6-Sep-10 TO 12-Sep-10

UNIT UNDER PLANNED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reason
Cent_Sect	KARPR1	220	1-Jul-08	00:10		Continued.	COH(En-Mass Coolant Clanel Replacement)
Koyna	ST-IV 1	250	16-Jul-10	00.00		Continued.	Preparing Work for 2nd Lake Tapping.
Koyna	ST-IV 2	250	16-Jul-10	00.00		Continued.	Preparing Work for 2nd Lake Tapping.
Koyna	ST - IV 3	250	16-Jul-10	00.00		Continued.	Preparing Work for 2nd Lake Tapping.
Koyna	ST - IV 4	250	16-Jul-10	00.00		Continued.	Preparing Work for 2nd Lake Tapping.
Cent_Sect	KARPR2	220	14-Aug-10	14:16		Continued.	Annual Overhaul.
Koradi	Unit 4	105	24-Aug-10	06.02		Continued.	Annual Overhaul.
Khaparkheda	Unit 2	210	27-Aug-10	23.40		Continued.	Capital Overhaul
Cent_Sect	NTPC(V-8)	500	20-Aug-10	00.46		Continued.	Annual Overhaul

UNIT UNDER FORCED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reason
Uran	Unit 2	60	4-Oct-08	19.00		Continued.	Gas Restriction
Uran	Unit 4	60	1-Apr-09	00:00		Continued.	Gas Restriction
Uran	Unit 3	60	16-Jun-10	19.52		Continued.	R.M.Work.
Parli	Unit 1	30	18-Jun-10	12:11		Continued.	For Scrapping.
Dabhol	2A	230	12-Jul-10	01.55		Continued.	Tripped due to Electrical Fault
Koradi	Unit 1	105	25-Aug-10	11.51	7-Sep-10	00.15	Boiler Inspection.
Bhusawal	Unit 1	58	1-Sep-10	23.30		Continued.	Wet Coal
Paras	Unit 3	250	4-Sep-10	00.06	7-Sep-10	12.11	CHP Belt replacement.
Paras	Unit 4	250	4-Sep-10	03.38	8-Sep-10	07.50	Bunkering problem.
Cent_Sect	Gandhar U3	144	4-Sep-10	00.09	9-Sep-10	18.30	Low demand.
Chandrapur	Unit 4	210	4-Sep-10	09.04	6-Sep-10	02.43	Tripped due to axial shift very high.
Parli	Unit 7	250	5-Sep-10	06.32	7-Sep-10	06.26	Steam Temp.low.
Bhusawal	Unit 3	210	5-Sep-10	08.55	7-Sep-10	10.34	Coal Mill Problem.
Parli	Unit 3	210	6-Sep-10	06.08	6-Sep-10	14.30	Tripped
Cent_Sect	NTPC(K-6)	500	5-Sep-10	23.50	7-Sep-10	02:24	Boiler tube leakage.
Cent_Sect	Kawas GT2A	106	3-Sep-10	20.14	9-Sep-10	16.10	Less Requisition
Chandrapur	Unit 3	210	6-Sep-10	05.05	6-Sep-10	09.30	Furnance Pressure Inadequate

Koradi	Unit 5	200	6-Sep-10	10.12	6-Sep-10	12.22	Auxiliary Supply Failed
Paras	Unit 2	55	6-Sep-10	12.30	6-Sep-10	14.30	Low Drum Level
Nasik	Unit 3	210	6-Sep-10	13.50	10-Sep-10	01.55	C.W.Pump leakage
Koradi	Unit 2	105	6-Sep-10	10.01	6-Sep-10	15.07	Tripped due to Occurrence at Koradi GCR
Parli	Unit 7	250	7-Sep-10	14.14	7-Sep-10	18.45	Drum Level Low
Parli	Unit 3	210	7-Sep-10	21.23	11-Sep-10	18.19	Low Furnance Pressure
Chandrapur	Unit 7	500	7-Sep-10	08.46	13-Sep-10	15.39	Flame Failure
Chandrapur	Unit 2	210	7-Sep-10	12.11	14-Sep-10	14.42	High Furnance Pressure
Chandrapur	Unit 3	210	7-Sep-10	09.53	10-Sep-10	08.24	High Furnance Pressure
Bhusawal	Unit 2	210	7-Sep-10	22.13	9-Sep-10	20.40	Boiler Tube Leakage
Chandrapur	Unit 6	500	8-Sep-10	06.32	8-Sep-10	16.26	Furnace Pressure High.
Koradi	Unit 5	200	8-Sep-10	10.33	11-Sep-10	06.25	Boiler Tube Leakage.
Dabhol	2X	290	8-Sep-10	02.53	9-Sep-10	08.45	AVR Autometic Air system prob.
Parli	Unit 7	250	8-Sep-10	02.05	8-Sep-10	05.00	Tripped, Main Steam Temp.Low
Dabhol	2B	230	8-Sep-10	02.53	9-Sep-10	07.42	AVR Autometic Air system prob.
Chandrapur	Unit 4	210	8-Sep-10	11.26	11-Sep-10	16.21	Boiler Tube Leakage.
Paras	Unit 4	250	8-Sep-10	16.05	8-Sep-10	18.17	Drum Level High.
Chandrapur	Unit 6	500	9-Sep-10	03.55	11-Sep-10	12.27	Flame Failure.
Koyna	Unit 11	80	9-Sep-10	21.10	10-Sep-10	21.00	Rotor E/F.
Bhusawal	Unit 2	210	9-Sep-10	21.30	10-Sep-10	22.48	Tripped on Wet Coal.
Bhusawal	Unit 3	210	9-Sep-10	14.52	9-Sep-10	22.48	Wet Coal Problem.
Parli	Unit 5	210	9-Sep-10	16.25	10-Sep-10	18.22	Low Drum Level.
Nasik	Unit 2	120	10-Sep-10	01.00		Continued.	Bunkering Problem.
Nasik	Unit 1	120	10-Sep-10	04.00	11-Sep-10	00.35	Bunkering problem.
Nasik	Unit 5	210	10-Sep-10	05.00	13-Sep-10	06.50	Condenser T/L.
Bhusawal	Unit 3	210	10-Sep-10	12.17	10-Sep-10	12.30	Vaccume pressure low.
Chandrapur	Unit 1	210	10-Sep-10	08.45	13-Sep-10	16.44	Economiser tube leakage.
Parli	Unit 2	30	3-Sep-10	14.10	12-Sep-10	18:20	BLR T/L.
Koradi	Unit 2	105	10-Sep-10	07.37	14-Sep-10	18.02	C.H.P.Problem.
Bhusawal	Unit 3	210	11-Sep-10	03.28	11-Sep-10	05.40	Furnace Pressure High.
Parli	Unit 6	250	11-Sep-10	12.17	11-Sep-10	13.41	Drum level high
Parli	Unit 3	210	11-Sep-10	18.31	11-Sep-10	19.50	Low vaccum problem.
Parli	Unit 5	210	11-Sep-10	20.50	12-Sep-10	00.25	Furnace pressure high.
Parli	Unit 7	250	11-Sep-10	13.56		Continued.	CHP Problem.
Chandrapur	Unit 5	500	12-Sep-10	05.05		Continued.	CW pump leakage.
Uran	Unit 6	108	12-Sep-10	05.05	12-Sep-10	07:56	Generator protection.
Paras	Unit 3	250	12-Sep-10	07:56	12-Sep-10	10:08	Loss of Fuel.
Bhusawal	Unit 2	210	12-Sep-10	22.16		Continued.	Due to occurance at 400KV Khadka.
Bhusawal	Unit 3	210	12-Sep-10	22.16		Continued.	Due to occurance at 400KV Khadka