

GENERATING UNIT OUTAGES FOR THE WEEK

FROM 13-Sep-10 TO 19-Sep-10

UNIT UNDER PLANNED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reason
Cent_Sect	KARPR1	220	1-Jul-08	00:10		Continued.	COH(En-Mass Coolant Clanel Replacement)
Koyna	ST-IV 1	250	16-Jul-10	00.00		Continued.	Preparing Work for 2nd Lake Tapping.
Koyna	ST-IV 2	250	16-Jul-10	00.00		Continued.	Preparing Work for 2nd Lake Tapping.
Koyna	ST - IV 3	250	16-Jul-10	00.00		Continued.	Preparing Work for 2nd Lake Tapping.
Koyna	ST - IV 4	250	16-Jul-10	00.00		Continued.	Preparing Work for 2nd Lake Tapping.
Cent_Sect	KARPR2	220	14-Aug-10	14:16		Continued.	Annual Overhaul.
Cent_Sect	NTPC(V-8)	500	20-Aug-10	00.46	16-Sep-10	17.39	Annual Overhaul
Koradi	Unit 4	105	24-Aug-10	06.02		Continued.	Annual Overhaul.
Khaparkheda	Unit 2	210	27-Aug-10	23.40		Continued.	Capital Overhaul
Nasik	Unit 4	210	15-Sep-10	10.55		Continued.	Annual Overhaul.
Cent_Sect	NTPC(V-6)	210	19-Sep-10	13.56		Continued.	Annual overhaul.

UNIT UNDER FORCED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reason
Uran	Unit 2	60	4-Oct-08	19.00		Continued.	Gas Restriction
Uran	Unit 4	60	1-Apr-09	00:00		Continued.	Gas Restriction
Uran	Unit 3	60	16-Jun-10	19.52		Continued.	R.M.Work.
Parli	Unit 1	30	18-Jun-10	12:11		Continued.	For Scrapping.
Dabhol	2A	230	12-Jul-10	01.55		Continued.	Tripped due to Electrical Fault
Bhusawal	Unit 1	58	1-Sep-10	23.30		Continued.	Wet Coal
Chandrapur	Unit 7	500	7-Sep-10	08.46	13-Sep-10	15.39	Flame Failure
Chandrapur	Unit 2	210	7-Sep-10	12.11	14-Sep-10	14.42	High Furnance Pressure
Nasik	Unit 2	120	10-Sep-10	01.00		Continued.	Bunkering Problem.
Nasik	Unit 5	210	10-Sep-10	05.00	13-Sep-10	06.50	Condenser T/L.
Chandrapur	Unit 1	210	10-Sep-10	08.45	13-Sep-10	16.44	Economiser tube leakage.
Koradi	Unit 2	105	10-Sep-10	07.37	14-Sep-10	18.02	C.H.P.Problem.
Parli	Unit 7	250	11-Sep-10	13.56	13-Sep-10	08.27	CHP Problem.
Chandrapur	Unit 5	500	12-Sep-10	05.05	13-Sep-10	04.46	CW pump leakage.
Bhusawal	Unit 2	210	12-Sep-10	22.16	13-Sep-10	01.12	Due to occurance at 400KV Khadka.
Bhusawal	Unit 3	210	12-Sep-10	22.16	13-Sep-10	01.34	Due to occurance at 400KV Khadka
Chandrapur	Unit 1	210	13-Sep-10	14.14	13-Sep-10	17.15	Low Vaccum.
Chandrapur	Unit 7	500	13-Sep-10	20.13	14-Sep-10	04.09	Flame failure.
Koradi	Unit 5	200	13-Sep-10	14.39	17-Sep-10	15.41	Condensor T/L.
Koradi	Unit 3	105	13-Sep-10	22.13	14-Sep-10	02.20	W/Dn.due to oil temprature problem.
Bhusawal	Unit 3	210	14-Sep-10	08.17	14-Sep-10	09.55	Flame Failure
Chandrapur	Unit 4	210	14-Sep-10	11.44	14-Sep-10	17.26	Furnance Pressure High
Parli	Unit 7	250	14-Sep-10	20.28	17-Sep-10	05.54	Bunkering Problem
Chandrapur	Unit 3	210	14-Sep-10	23.38		Continued.	Furnance Pressure High
Nasik	Unit 3	210	14-Sep-10	23.55	15-Sep-10	05.40	Flame Failure
Parli	Unit 6	250	15-Sep-10	07.30	17-Sep-10	08.57	Coal Shortage.
Chandrapur	Unit 2	210	15-Sep-10	16.37	15-Sep-10	21.05	Low Vaccum.
Bhusawal	Unit 3	210	16-Sep-10	12.25	16-Sep-10	14.30	Furnace Pressure High.
Parli	Unit 2	30	16-Sep-10	15.20		Continued.	Furnace Pressure High.
Uran	Unit 6	108	17-Sep-10	00.37	17-Sep-10	05.04	Excitation X'mer Problem.
Parli	Unit 3	210	17-Sep-10	05.33		Continued.	Furnance Pressure High
Bhusawal	Unit 3	210	17-Sep-10	06.15	18-Sep-10	01.30	Tripped,No Coal Flow.
Parli	Unit 7	250	17-Sep-10	16.15	19-Sep-10	07.10	High Furnance Pressure.
Parli	Unit 5	210	17-Sep-10	14.07		Continued.	Furnance Pressure High.
Chandrapur	Unit 1	210	17-Sep-10	08.29	17-Sep-10	10.23	Furnance Pressure High.
Chandrapur	Unit 4	210	17-Sep-10	05.53	18-Sep-10	05.05	Main Steam Temp.Low.
Chandrapur	Unit 2	210	18-Sep-10	00.20		Continued.	Furnance Pressure High.
Bhusawal	Unit 3	210	18-Sep-10	10.51	18-Sep-10	11.48	Due to bunkering problem.
Parli	Unit 4	210	18-Sep-10	20.13	20-Sep-10	03.06	High furnace pressure.
CPP	JSW_JAIGAD	300	18-Sep-10	16.00		Continued.	Planned shutdown.
Bhusawal	Unit 3	210	19-Sep-10	07.43	19-Sep-10	11.18	W/Dn.due to Blr, tripped.
Koradi	Unit 1	105	19-Sep-10	18.18		Continued.	Boiler tube leakage.