

GENERATING UNIT OUTAGES FOR THE WEEK

FROM 18-Oct-10 TO 24-Oct-10

UNIT UNDER PLANNED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reason
Cent_Sect	KARPR1	220	1-Jul-08	00:10		Continued.	COH(En-Mass Coolant Clanel Replacement)
Koyna	ST-IV 1	250	16-Jul-10	00.00		Continued.	Preparing Work for 2nd Lake Tapping.
Koyna	ST-IV 2	250	16-Jul-10	00.00		Continued.	Preparing Work for 2nd Lake Tapping.
Koyna	ST - IV 3	250	16-Jul-10	00.00		Continued.	Preparing Work for 2nd Lake Tapping.
Koyna	ST - IV 4	250	16-Jul-10	00.00		Continued.	Preparing Work for 2nd Lake Tapping.
Koradi	Unit 4	105	24-Aug-10	06.02		Continued.	Annual Overhaul.
Nasik	Unit 4	210	15-Sep-10	10.55		Continued.	Annual Overhaul.
Cent_Sect	Tarapur 1	80	10-Oct-10	21.30		Continued.	Fuel refuelling.

UNIT UNDER FORCED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reason
Uran	Unit 2	60	4-Oct-08	19.00		Continued.	Gas Restriction
Uran	Unit 4	60	1-Apr-09	00:00		Continued.	Gas Restriction
Uran	Unit 3	60	16-Jun-10	19.52		Continued.	R.M.Work.
Dabhol	2A	230	12-Jul-10	01.55		Continued.	Tripped due to Electrical Fault
Parli	Unit 5	210	16-Oct-10	00.08	21-Oct-10	06.54	STN.T/F I and II Trip.
Khaparkheda	Unit 4	210	17-Oct-10	01.01	18-Oct-10	04.11	Boiler tube leakage.
Nasik	Unit 2	120	17-Oct-10	02.50	21-Oct-10	01.30	Boiler tube leakage.
Chandrapur	Unit 7	500	17-Oct-10	07.09	18-Oct-10	08.11	Master fuel trip.
Chandrapur	Unit 2	210	17-Oct-10	22.04	18-Oct-10	01.24	Furnace Pressure High.
Parli	Unit 1	30	18-Oct-10	01.52	18-Oct-10	13.09	Flame failure.
Nasik	Unit 5	210	18-Oct-10	10.40	18-Oct-10	13.45	Boiler Aux.Trf.Trip.
Bhusawal	Unit 3	210	18-Oct-10	22.07	20-Oct-10	20.35	HP turbine side control valve problem.
Chandrapur	Unit 2	210	19-Oct-10	00.01	19-Oct-10	02.19	Furnace pressure high.
Parli	Unit 1	30	19-Oct-10	12.04	19-Oct-10	15.42	Furnace pressure high.
Uran	Unit 6	108	19-Oct-10	23.44	20-Oct-10	01.02	Turbine casing vibration.
Cent_Sect	NTPC(K-5)	500	19-Oct-10	21.43	20-Oct-10	20.42	Boiler tube leakage.
Uran	Unit 6	108	20-Oct-10	03.14	20-Oct-10	05.05	Turbine casing vibration.
Uran	Unit 5	108	20-Oct-10	01.43	20-Oct-10	03.11	Drum level high.
Uran	Unit A0	120	20-Oct-10	01.43	20-Oct-10	11.19	A2 drum level high.
Paras	Unit 3	250	20-Oct-10	17.33	20-Oct-10	19.50	Flame Failure.
Paras	Unit 4	250	20-Oct-10	13.52	20-Oct-10	16.15	Flame Failure.
Koradi	Unit 6	210	21-Oct-10	23.12	23-Oct-10	06.36	High Falme Failure.
Cent_Sect	Sipat-4	500	22-Oct-10	05.15	23-Oct-10	10.17	Boiler Tube Leakage.
Cent_Sect	NTPC(V-10)	500	22-Oct-10	07:27	24-Oct-10	16.08	Boiler Tube Leakage.
REL	1	250	23-Oct-10	11.30	23-Oct-10	13.43	Tripped on REF.
Parli	Unit 1	30	23-Oct-10	05.44	24-Oct-10	11.57	Flame Failure.
Parli	Unit 2	30	23-Oct-10	05.15	24-Oct-10	02.02	Flame Failure.
Bhusawal	Unit 2	210	24-Oct-10	00.45	24-Oct-10	03.20	Flame Failure.
Uran	Unit 5	108	24-Oct-10	02.30		Continued.	CTO Temp.High.
Uran	Unit A0	120	24-Oct-10	02.30		Continued.	CTO Temp.High.
Uran	Unit 6	108	24-Oct-10	02.30	24-Oct-10	04.00	CTO Temp.High.
Parli	Unit 3	210	24-Oct-10	03.07	24-Oct-10	14.46	Furnace Pressure High.
Chandrapur	Unit 4	210	24-Oct-10	06.11	24-Oct-10	10.04	Furnace Pressure High.
Koradi	Unit 7	210	24-Oct-10	23.28	25-Oct-10	03.24	Furnace pressure hogh.
CPP	JSW_JAIGAD	300	25-Oct-10	00.43		Continued.	Bus fault at New Koyna.