

GENERATING UNIT OUTAGES FOR THE WEEK

FROM 21-Jun-10 TO 27-Jun-10

UNIT UNDER PLANNED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reason
Cent_Sect	KARPR1	220	1-Jul-08	00:10		Continued.	COH(En-Mass Coolant Clanel Replacement)
Chandrapur	Unit 6	500	1-Apr-10	01.15		Continued.	Annual Overhaul
Chandrapur	Unit 1	210	8-Apr-10	08.36	24-Jun-10	02.48	Annual Overhaul
Dabhol	2B	230	15-Apr-10	01.40	25-Jun-10	14.31	Control System modification work
Chandrapur	Unit 5	500	16-Apr-10	15.49		Continued.	Water Balancing Problem.
Chandrapur	Unit 2	210	18-Apr-10	21.38	25-Jun-10	21.20	Clinker Formation.
Chandrapur	Unit 7	500	25-Apr-10	00.23		Continued.	Water Balancing Problem.
Chandrapur	Unit 3	210	26-May-10	23.59		Continued.	Water Balancing Problem.
Chandrapur	Unit 1	210	24-Jun-10	08.41	27-Jun-10	06.10	AVR Replacement.
Koradi	Unit 5	200	26-Jun-10	02:33		Continued.	Annual overhaul

UNIT UNDER FORCED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reason
Uran	Unit 2	60	4-Oct-08	19.00		Continued.	Gas Restriction
Uran	Unit 4	60	1-Apr-09	00:00		Continued.	Gas Restriction
Paras	Unit 2	55	13-Jun-10	17.35		Continued.	For Scrapping.
Paras	Unit 4	250	15-Jun-10	20.55		Continued.	Clinker Formation.
Uran	Unit 3	60	16-Jun-10	19.52		Continued.	R.M.Work.
Tata	Trombay 4	150	18-Jun-10	01.40		Continued.	Low demand.
Bhusawal	Unit 1	58	18-Jun-10	05.10		Continued.	For scrapping.
Parli	Unit 2	30	18-Jun-10	06.26		Continued.	For Scrapping.
Parli	Unit 1	30	18-Jun-10	12.11		Continued.	For scrapping.
Dabhol	1B	230	18-Jun-10	13.09		Continued.	Unit Differential.
Dabhol	1A	230	18-Jun-10	13.09		Continued.	Unit Differential.
Dabhol	1X	290	18-Jun-10	13.09		Continued.	Unit differential.
Bhusawal	Unit 3	210	19-Jun-10	12.41	22-Jun-10	03.50	Boiler Tube Leakage
Koradi	Unit 2	105	20-Jun-10	08.06	23-Jun-10	22.48	Coal Problem.
Koradi	Unit 4	105	20-Jun-10	18.44	27-Jun-10	18.17	Boiler Tube Leakage.
Koradi	Unit 5	200	21-Jun-10	11.17	24-Jun-10	00.39	Bunkering Problem.
Parli	Unit 6	250	21-Jun-10	15.10	21-Jun-10	19.05	Furnace Pressure High.
Khaparkheda	Unit 3	210	21-Jun-10	15.22	21-Jun-10	22.10	Flame Failure.
Nasik	Unit 3	210	21-Jun-10	22.05	27-Jun-10	08.45	Boiler Hopper Leakage.
Uran	Unit 7	108	22-Jun-10	00.35	23-Jun-10	10.20	Filter Replacement.
Parli	Unit 5	210	23-Jun-10	02.44	23-Jun-10	08.21	Drum level very high.
Tata	Trombay 8	250	23-Jun-10	01.15	23-Jun-10	04.50	Header pressure low.
Parli	Unit 5	210	23-Jun-10	08.37	23-Jun-10	13.45	Drum level low.
Koyna	ST - IV 4	250	23-Jun-10	07.50		Continued.	Servomotor seal replacement.
Parli	Unit 7	250	24-Jun-10	14.18	24-Jun-10	19.00	Steam problem.
Khaparkheda	Unit 2	210	24-Jun-10	19.50	24-Jun-10	23.00	Flame flure.
Parli	Unit 4	210	24-Jun-10	23.18		Continued.	HPCV problem.
Paras	Unit 3	250	25-Jun-10	02.26	25-Jun-10	04.21	Clinker problem.
Uran	Unit 6	108	25-Jun-10	04.45	25-Jun-10	09.25	Rectifire fault
Chandrapur	Unit 2	210	25-Jun-10	21.25	26-Jun-10	01.34	Tripped due to failure of Stn Supply
REL	2	250	26-Jun-10	02.19		Continued.	Condensor Tube Leakage
Dabhol	2B	230	26-Jun-10	06.48	26-Jun-10	20.14	PPM trial
Parli	Unit 7	250	26-Jun-10	19.07	26-Jun-10	21.18	Tripped due to Turbine tripped
Dabhol	3A	230	27-Jun-10	00.20		Continued.	Boiler Tube Leakage
Chandrapur	Unit 1	210	27-Jun-10	10.10	27-Jun-10	12:45	Main Steam Temp.Low.
Koradi	Unit 6	210	27-Jun-10	13.53		Continued.	Furnace Pressure High.
Cent_Sect	NTPC(K-4)	500	27-Jun-10	18:57		Continued.	Boiler Tube Leakage.
Dabhol	2A	230	28-Jun-10	02.39		Continued.	U.A.Tr.Tripped.
Koradi	Unit 1	105	28-Jun-10	05.53		Continued.	Low Bunkering