

GENERATING UNIT OUTAGES FOR THE WEEK

FROM 2-Apr-12 TO 8-Apr-12

UNIT UNDER PLANNED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reasondes
Koyna	UNIT 6	75	10-Mar-12	7.05	2-Apr-12	12.25	Pressure Shaft work
Chandrapur	Unit 1	210	11-Mar-12	8.48		Continued.	Annual Overhaul
Cent_Sect	NTPC(V-2)	210	1-Apr-12	0:01		Continued.	AOH.
Cent_Sect	NTPC(K-6)	500	9-Apr-12	0.09		Continued.	Annual Overhaul

UNIT UNDER FORCED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reason
Tata	Trombay 4	150	14-Feb-12	0.08		Continued.	Withdrawn/Cold Standby
Cent_Sect	TARAPUR-3	540	15-Mar-12	22.13	5-Apr-12	19.07	Primary coolant pump fail.
Parli	Unit 3	210	23-Mar-12	23.57	5-Apr-12	15.55	Coal shortage.
Bhusawal	Unit 4	500	25-Mar-12	17.37	2-Apr-12	10:04	Gen.Protection.
Dabhol	1A	230	30-Mar-12	23.29		Continued.	Gas Shortage
Bhusawal	Unit 5	500	30-Mar-12	4.34		Continued.	Hand Tripped
Dabhol	1B	230	31-Mar-12	19:45		Continued.	Maintenance work.
Dabhol	1X	290	31-Mar-12	19:43		Continued.	Maintenance work.
CPP	WPCL U-1	135	1-Apr-12	11:49	30-Apr-12	13:26	P T Problem.
Khaparkheda	Unit 3	210	2-Apr-12	4:03	3-Apr-12	20.23	Boiler Tube Leakage.
Khaparkheda	Unit 5	500	2-Apr-12	20.07	3-Apr-12	0.13	Cooling Gas Temperature High
Tata	Trombay 5	500	3-Apr-12	2	3-Apr-12	10.38	Hot Spot on Gen.T/F Neutral Bushing
Koradi	Unit 6	210	4-Apr-12	5.5	4-Apr-12	23.32	Air Heater 'B' Decoupled
Bhusawal	Unit 4	500	4-Apr-12	8.08	4-Apr-12	15.05	Class A protection operated.
Parli	Unit 5	210	4-Apr-12	21.38		Continued.	Coal shortage.
Khaparkheda	Unit 5	500	5-Apr-12	10.15	6-Apr-12	15.42	Low furnace pressure.
Bhusawal	Unit 4	500	6-Apr-12	0.03	6-Apr-12	4.2	Generator problem.
Uran	Unit A0	120	6-Apr-12	5.3	6-Apr-12	12.33	Trip,due to jurk.
Uran	Unit B0	120	6-Apr-12	5.3	6-Apr-12	16.55	Trip,due to jurk.
Uran	Unit 5	108	6-Apr-12	5.3	6-Apr-12	7.56	Trip,due to jurk.
Uran	Unit 6	108	6-Apr-12	5.3	6-Apr-12	9.11	Trip,due to jurk.
Uran	Unit 8	108	6-Apr-12	6.28	6-Apr-12	15.4	Trip due to jerk.
Bhusawal	Unit 4	500	6-Apr-12	20.02	7-Apr-12	13:18	Class protection operated.
Bhusawal	Unit 3	210	6-Apr-12	21.35	7-Apr-12	22.39	Main steam line leakage.
Koyna	Unit 12	80	6-Apr-12	19.4	7-Apr-12	4.15	Rotor earth fault.
Koyna	Unit 1	75	6-Apr-12	14.15	7-Apr-12	21.55	TGB cooler replacement work.
Koyna	Unit 6	75	7-Apr-12	13.45		Continued.	Oil Level Sensor problem
Koyna	Unit 8	80	8-Apr-12	7.3	8-Apr-12	19.25	Preventive maint.work
Dabhol	3A	230	8-Apr-12	21.13	8-Apr-12	22.44	Tripped on CW Pump
Dabhol	3B	230	8-Apr-12	21.13	9-Apr-12	2.08	Tripped on CW Pump
Dabhol	3X	290	8-Apr-12	21.13	8-Apr-12	23.57	Tripped on CW Pump
Parli	Unit 3	210	9-Apr-12	0.1		Continued.	PA Fan Tripped