

GENERATING UNIT OUTAGES FOR THE PERIOD

FROM 4-Oct-10 TO 10-Oct-10

UNIT UNDER PLANNED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reason
Cent_Sect	KARPR1	220	1-Jul-08	00:10		Continued.	COH(En-Mass Coolant Clanel Replacement)
Koyna	ST-IV 1	250	16-Jul-10	00.00		Continued.	Preparing Work for 2nd Lake Tapping.
Koyna	ST-IV 2	250	16-Jul-10	00.00		Continued.	Preparing Work for 2nd Lake Tapping.
Koyna	ST - IV 3	250	16-Jul-10	00.00		Continued.	Preparing Work for 2nd Lake Tapping.
Koyna	ST - IV 4	250	16-Jul-10	00.00		Continued.	Preparing Work for 2nd Lake Tapping.
Koradi	Unit 4	105	24-Aug-10	06.02		Continued.	Annual Overhaul.
Khaparkheda	Unit 2	210	27-Aug-10	23.40	8-Oct-10	19.39	Capital Overhaul
Nasik	Unit 4	210	15-Sep-10	10.55		Continued.	Annual Overhaul.
Cent_Sect	NTPC(V-6)	210	19-Sep-10	13.56		Continued.	Annual overhaul.
Cent_Sect	sipat-5	500	4-Oct-10	01.58	9-Oct-10	21.23	Boiler revalidation.
Cent_Sect	TARAPUR-3	540	3-Oct-10	22.03		Continued.	Steam line work.
Cent_Sect	Tarapur 1	80	10-Oct-10	21.30		Continued.	Fuel refuelling.

UNIT UNDER FORCED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reason
Uran	Unit 2	60	4-Oct-08	19.00		Continued.	Gas Restriction
Uran	Unit 4	60	1-Apr-09	00:00		Continued.	Gas Restriction
Uran	Unit 3	60	16-Jun-10	19.52		Continued.	R.M.Work.
Parli	Unit 1	30	18-Jun-10	12:11	9-Oct-10	23.56	For Scrapping.
Dabhol	2A	230	12-Jul-10	01.55		Continued.	Tripped due to Electrical Fault
Nasik	Unit 2	120	10-Sep-10	01.00	5-Oct-10	13.35	Bunkering Problem.
Koradi	Unit 6	210	29-Sep-10	18.41	4-Oct-10	11.17	Air Reheater Tripped.
Koradi	Unit 1	105	2-Oct-10	13.38	4-Oct-10	16.27	BLR T/L.

Tata	Trombay 7B	60	4-Oct-10	02.22	4-Oct-10	04.03	Low vaccum
Khaparkheda	Unit 3	210	4-Oct-10	09.42	4-Oct-10	12.26	Tripped on flame failure.
Khaparkheda	Unit 3	210	4-Oct-10	12.34	4-Oct-10	14.22	Gas temperature high.
CPP	JSW_JAIGAD	300	4-Oct-10	20.00	5-Oct-10	04.06	Tripped
CPP	JSW_JAIGAD	300	5-Oct-10	04.40	5-Oct-10	06.38	Parameter variation.
Bhusawal	Unit 2	210	5-Oct-10	08.00	5-Oct-10	08.56	Furnace draught.
Parli	Unit 6	250	5-Oct-10	11.58	5-Oct-10	17.29	less air flow.
Paras	Unit 2	55	5-Oct-10	09.10	5-Oct-10	17.30	BFP Problem.
Chandrapur	Unit 1	210	5-Oct-10	13.48	5-Oct-10	17.10	Furnace pressure high.
Nasik	Unit 2	120	5-Oct-10	16.55	6-Oct-10	19:00	HP Differential.
CPP	JSW_JAIGAD	300	6-Oct-10	03.37	9-Oct-10	17.50	Cooling water.
Koradi	Unit 1	105	6-Oct-10	07:13	8-Oct-10	04.32	BTL.
Bhusawal	Unit 1	58	7-Oct-10	02:00	9-Oct-10	12.35	BTL.
Uran	Unit 6	108	7-Oct-10	00:33	8-Oct-10	18.46	Filter Repl.
Nasik	Unit 1	120	7-Oct-10	06.35	10-Oct-10	01.40	Boiler Tube Leakage.
Cent_Sect	NTPC(K-6)	500	8-Oct-10	16.55	10-Oct-10	02.52	Boiler Tube Leakage.
Khaparkheda	Unit 2	210	9-Oct-10	03.42	9-Oct-10	06.24	Lubricant on Oil Pressure.
Parli	Unit 4	210	9-Oct-10	11.08		Continued.	BLR T/L.
Uran	Unit A0	120	9-Oct-10	16.05	9-Oct-10	19.18	Clean tank drain level high.
Uran	Unit 5	108	9-Oct-10	16.05	9-Oct-10	16.47	Damper discripeincy.
Parli	Unit 3	210	9-Oct-10	15.02	9-Oct-10	19.03	RCF supply fail.
Khaparkheda	Unit 2	210	9-Oct-10	14.14	9-Oct-10	17.24	Lubricating oil pressure low.
Dabhol	1B	230	10-Oct-10	00.29		Continued.	Flue gas leakage in turbine compartment.
Bhusawal	Unit 2	210	10-Oct-10	05.20		Continued.	BLR T/L.
Uran	Unit 6	108	10-Oct-10	20.05	10-Oct-10	20.50	C.T.O.high
Uran	Unit 8	108	10-Oct-10	20.05		Continued.	C.T.O.high
Bhusawal	Unit 1	58	10-Oct-10	18.10		Continued.	T/L.