

GENERATING UNIT OUTAGES FOR THE WEEK

FROM 12-Sep-11 TO 18-Sep-11

UNIT UNDER PLANNED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reasondes
Chandrapur	Unit 4	210	16-Aug-11	00.04		Continued.	Annual Overhaul.
Paras	Unit 3	250	19-Aug-11	16.33		Continued.	Annual Overhaul.
Bhusawal	Unit 2	210	22-Aug-11	15.27		Continued.	AOH.
Parli	Unit 4	210	31-Aug-11	01.07		Continued.	Annual Overhaul.
Koradi	Unit 5	200	3-Sep-11	16.46		Continued.	I.D Fan problem. Mini Overhaul
Dabhol	1B	230	5-Sep-11	23.57		Continued.	Generator Inspection
Nasik	Unit 4	210	7-Sep-11	20.03		Continued.	Wet coal problem.Mini Overhaul
Cent_Sect	NTPC(V-5)	210	14-Sep-11	00.41		Continued.	Annual Overhaul.

UNIT UNDER FORCED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reason
Dabhol	2B	230	5-Sep-11	23.08	12-Sep-11	08.03	Differential Pressure across STG(2X)Main Steam Control Valve increased
Dabhol	2A	230	5-Sep-11	23.01	12-Sep-11	17.39	Differential Pressure across STG(2X)Main Steam Control Valve increased
Dabhol	2X	290	5-Sep-11	23.08	12-Sep-11	11.19	Differential Pressure across STG(2X)Main Steam Control Valve increased
Cent_Sect	NTPC(K-4)	500	8-Sep-11	14.26		Continued.	Ash handling problem.
Cent_Sect	NTPC(K-5)	500	8-Sep-11	14.52		Continued.	Ash handling problem.
Cent_Sect	NTPC(K-6)	500	8-Sep-11	15.03	16-Sep-11	09.45	Ash handling problem.
Bhusawal	Unit 3	210	9-Sep-11	07.48	12-Sep-11	07.43	Low Drum Level
Cent_Sect	NTPC(K-1)	210	9-Sep-11	18.18	14-Sep-11	17.51	Circulation Problem
Khaparkheda	Unit 2	210	11-Sep-11	21.15	18-Sep-11	00.33	Flame Failure
Parli	Unit 5	210	11-Sep-11	21.04	12-Sep-11	01.05	Boiler Protection
CPP	WPCL U-2	135	11-Sep-11	08.12		Continued.	Withdrawn
Khaparkheda	Unit 5	500	12-Sep-11	05.55		Continued.	Generator Protection.
Parli	Unit 3	210	12-Sep-11	09.25	12-Sep-11	15.55	System Problem.
Cent_Sect	NTPC(V-8)	500	12-Sep-11	20.20	13-Sep-11	20.18	Tripped.
Bhusawal	Unit 3	210	12-Sep-11	22.31	13-Sep-11	02.50	Boiler Problem.
Uran	Unit 8	108	12-Sep-11	22.10	13-Sep-11	06.12	Exitusion T/F Oil Leakage.
Bhusawal	Unit 3	210	13-Sep-11	03.40	13-Sep-11	21.29	Boiler Problem.
Uran	Unit 8	108	13-Sep-11	06.38	13-Sep-11	13.26	Earth Fault.
CPP	JSW (J) U3	300	13-Sep-11	12.20	13-Sep-11	18.55	Elect System Problem.
Cent_Sect	NTPC (K-2)	210	13-Sep-11	10.11	13-Sep-11	20.25	Low Vaccum.
CPP	JSW (J) U3	300	13-Sep-11	19.12	14-Sep-11	10.55	Turbine Problem.
Chandrapur	Unit 6	500	13-Sep-11	22.40	17-Sep-11	03.26	Boiler Tube Leakage.
Uran	Unit 5	108	14-Sep-11	01.20	14-Sep-11	02.31	Hydac System Failure.
Bhusawal	Unit 3	210	14-Sep-11	05.57	14-Sep-11	08.15	Furnace Pressure Low.
Koyna	Unit 12	80	14-Sep-11	12.07	14-Sep-11	14.00	Distance Protection.
Bhusawal	Unit 3	210	14-Sep-11	12.38	14-Sep-11	14.08	Drum level high.
Koradi	Unit 7	210	14-Sep-11	12.45	14-Sep-11	17.55	Furnace Pressure high.
Cent_Sect	NTPC(K-7)	500	14-Sep-11	21.37		Continued.	G/T problem.
Koyna	ST - IV 4	250	14-Sep-11	22.32	15-Sep-11	04.45	Preventive maintenance.
Uran	Unit 7	108	15-Sep-11	00.10	16-Sep-11	00.07	Filter replacement.
Parli	Unit 3	210	16-Sep-11	03.15	17-Sep-11	13.04	Bunkring Problem.
Uran	Unit 7	108	16-Sep-11	03.05	16-Sep-11	12.24	Fire in flue gas outlet duct.
Nasik	Unit 5	210	16-Sep-11	10.05		Continued.	Boiler tube leakage.
Cent_Sect	NTPC(K-1)	210	18-Sep-11	11.31		Continued.	Ash Handling Problem
Cent_Sect	NTPC (K-2)	210	18-Sep-11	11.31	18-Sep-11	17.03	Ash Handling Problem
Cent_Sect	NTPC(K-3)	210	18-Sep-11	11.31		Continued.	Ash Handling Problem
Cent_Sect	NTPC(K-6)	500	18-Sep-11	11.31		Continued.	Ash Handling Problem
Chandrapur	Unit 3	210	18-Sep-11	17.30	18-Sep-11	23.38	Coal Shortage