

GENERATING UNIT OUTAGES FOR THE WEEK

FROM 14-Jun-10 TO 20-Jun-10

UNIT UNDER PLANNED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reason
Cent_Sect	KARPR1	220	1-Jul-08	00:10		Continued.	COH(En-Mass Coolant Clnel Replacement)
Chandrapur	Unit 6	500	1-Apr-10	01.15		Continued.	Annual Overhaul
Chandrapur	Unit 1	210	8-Apr-10	08.36		Continued.	Annual Overhaul
Dabhol	2B	230	15-Apr-10	01.40		Continued.	Control System modification work
Chandrapur	Unit 5	500	16-Apr-10	15.49		Continued.	Water Balancing Problem.
Chandrapur	Unit 2	210	18-Apr-10	21.38		Continued.	Clinker Formation.
Chandrapur	Unit 7	500	25-Apr-10	00.23		Continued.	Water Balancing Problem.
Cent_Sect	NTPC(K-4)	500	9-May-10	07.00	14-Jun-10	22.05	Annual Overhaul
Chandrapur	Unit 3	210	26-May-10	23.59		Continued.	Water Balancing Problem.
Koyna	ST - IV 3	250	11-Jun-10	08.00	19-Jun-10	17.00	Maintenance work
Koyna	ST-IV 2	250	19-Jun-10	11.30	19-Jun-10	15.30	Inspection of Injection Gate(Civil work)
Koyna	ST-IV 1	250	19-Jun-10	11.30	19-Jun-10	15.30	Inspection of Injection Gate(Civil Work)
Koyna	ST - IV 4	250	19-Jun-10	11.30	19-Jun-10	15.30	Inspection of Injection Gate(Civil work)

UNIT UNDER FORCED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reason
Uran	Unit 2	60	4-Oct-08	19.00		Continued.	Gas Restriction
Uran	Unit 4	60	1-Apr-09	00:00		Continued.	Gas Restriction
Koradi	Unit 2	105	9-Jun-10	09.06	18-Jun-10	02.43	Wind box red hot.
Bhusawal	Unit 2	210	12-Jun-10	14.03	15-Jun-10	00.57	ID Fan problem.
Nasik	Unit 4	210	13-Jun-10	08.27	14-Jun-10	23.29	Water Value Tube Leakage.
Paras	Unit 2	55	13-Jun-10	17.35		Continued.	Coal Cycle Problem.
Koradi	Unit 6	210	14-Jun-10	15.20	18-Jun-10	15.07	I D Fan Problem.
Koradi	Unit 4	105	14-Jun-10	22.57	16-Jun-10	21.32	Boiler Tube Leakage.
Bhusawal	Unit 2	210	15-Jun-10	08.55	18-Jun-10	22.04	BLR T/L.
Uran	Unit 3	60	15-Jun-10	12.10	16-Jun-10	07.55	W/Dn.
Dabhol	2A	230	15-Jun-10	08.59	15-Jun-10	14.39	Electrical fault.
Dabhol	2X	290	15-Jun-10	08.59	15-Jun-10	15.35	W/Dn.
Paras	Unit 4	250	15-Jun-10	20.55		Continued.	Clinker Formation.
Nasik	Unit 4	210	15-Jun-10	22.42	16-Jun-10	01.25	Repl.of Turbine Trip Solenoid Coil.
Khaparkheda	Unit 4	210	15-Jun-10	17.16	17-Jun-10	19.38	Boiler Tube Leakage.
Tata	Trombay 7B	60	16-Jun-10	08.52	16-Jun-10	19.11	Turbine pressure high.
Tata	Trombay 7B	60	16-Jun-10	19.36	17-Jun-10	07.18	Turbine pressure high.
Uran	Unit 3	60	16-Jun-10	19.52		Continued.	R.M.Work.
Koradi	Unit 4	105	16-Jun-10	24.00	17-Jun-10	09.04	Compressor discharge line probelm.
Dabhol	2A	230	17-Jun-10	11.52	17-Jun-10	15.13	Tie breaker R Ph.burst.
Nasik	Unit 1	120	17-Jun-10	03.05	18-Jun-10	23.40	Boiler Tube Leakage.
Uran	Unit B0	120	17-Jun-10	12.03	17-Jun-10	14.05	Generator prot. trip.
Uran	Unit 7	108	17-Jun-10	12.05	17-Jun-10	12.44	Trip.
Uran	Unit 8	108	17-Jun-10	12.04	17-Jun-10	12.22	Trip.
Dabhol	2X	290	17-Jun-10	11.32	17-Jun-10	22.02	Tie breaker R Ph.burst.
Tata	Trombay 4	150	18-Jun-10	01.40		Continued.	Low demand.
Bhusawal	Unit 1	58	18-Jun-10	05.10		Continued.	For scraping.
Parli	Unit 5	210	18-Jun-10	16.50	18-Jun-10	21.00	Load variation.
Parli	Unit 2	30	18-Jun-10	06.26		Continued.	For Scraping.
Parli	Unit 1	30	18-Jun-10	12.11		Continued.	For scraping.
Dabhol	1B	230	18-Jun-10	13.09		Continued.	Unit Differential.
Dabhol	1A	230	18-Jun-10	13.09		Continued.	Unit Differential.
Dabhol	1X	290	18-Jun-10	13.09		Continued.	Unit differential.
Bhusawal	Unit 3	210	19-Jun-10	12.41		Continued.	Boiler Tube Leakage
Parli	Unit 5	210	19-Jun-10	12.10	19-Jun-10	16.53	Furnance pressure high
Nasik	Unit 5	210	19-Jun-10	18.50	19-Jun-10	21.10	Loss of Fuel
Koradi	Unit 2	105	19-Jun-10	14.35	19-Jun-10	21.32	Tripped on Mal Functioning of over Frequency
Koradi	Unit 6	210	19-Jun-10	16.01	19-Jun-10	18.08	Aux.supply fail
Tata	Trombay 8	250	19-Jun-10	08.27	19-Jun-10	14.14	Loss of Fuel
Koradi	Unit 2	105	20-Jun-10	08.06		Continued.	Coal Problem.
Parli	Unit 6	250	20-Jun-10	02.25	20-Jun-10	06.27	ID Fan Problem.
Koradi	Unit 4	105	20-Jun-10	18.44		Continued.	Boiler Tube Leakage.