

GENERATING UNIT OUTAGES FOR THE PERIOD

FROM 19-Jul-10 TO 25-Jul-10

UNIT UNDER PLANNED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reason
Cent_Sect	KARPR1	220	1-Jul-08	00:10		Continued.	COH(En-Mass Coolant Clanel Replacement)
Chandrapur	Unit 3	210	26-May-10	23.59		Continued.	Water Balancing Problem.
Koradi	Unit 5	200	26-Jun-10	02:33	28-Jul-10	14.27	Annual Overhaul.
Cent_Sect	NTPC (K-2)	210	30-Jun-10	23.46	27-Jul-10	02:19	Annual Overhaul.
Cent_Sect	NTPC(V) 9	500	1-Jul-10	00.04	26-Jul-10	16.29	Annual Overhaul.
Cent_Sect	Kawas ST2C	116	1-Jul-10	00.08		Continued.	Annual Overhaul.
Parli	Unit 4	210	5-Jul-10	09.27		Continued.	Capital Overhaul
Koyna	ST-IV 1	250	16-Jul-10	00.00		Continued.	Preparing work for 2nd lake tapping.
Koyna	ST-IV 2	250	16-Jul-10	00.00		Continued.	preparing work for 2nd lake tapping.
Koyna	ST - IV 3	250	16-Jul-10	00.00		Continued.	Preparing work for 2nd lake tapping.
Koyna	ST - IV 4	250	16-Jul-10	00.00		Continued.	preparing work for 2nd lake tapping.
Tata	Trombay 7A	120	25-Jul-10	17.39		Continued.	Main T/F replacement
Tata	Trombay 7B	60	25-Jul-10	15.45		Continued.	Inspection and Maint.work

UNIT UNDER FORCED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reason
Uran	Unit 2	60	4-Oct-08	19.00		Continued.	Gas Restriction
Uran	Unit 4	60	1-Apr-09	00:00		Continued.	Gas Restriction
Paras	Unit 2	55	13-Jun-10	17.35		Continued.	For Scrapping.
Uran	Unit 3	60	16-Jun-10	19.52		Continued.	R.M.Work.
Tata	Trombay 4	150	18-Jun-10	01.40	25-Jul-10	13.45	Low demand.
Dabhol	1B	230	18-Jun-10	13.09		Continued.	Unit Differential.
Dabhol	1A	230	18-Jun-10	13.09		Continued.	Unit Differential.
Dabhol	1X	290	18-Jun-10	13.09		Continued.	Unit Differential.
Bhusawal	Unit 1	58	18-Jun-10	05:10	20-Jul-10	12.45	For Scrapping.
Parli	Unit 2	30	18-Jun-10	06:26		Continued.	For Scrapping.
Parli	Unit 1	30	18-Jun-10	12:11		Continued.	For Scrapping.
Cent_Sect	TARAPUR-4	540	28-Jun-10	05.54	22-Jul-10	16.28	System Deficiency.
Koradi	Unit 4	105	6-Jul-10	10.03		Continued.	Boiler Tube Leakage.
Parli	Unit 7	250	6-Jul-10	23.03	20-Jul-10	23.47	Generator Protection Operated.
Koradi	Unit 2	105	9-Jul-10	07.46	19-Jul-10	09.42	Boiler Tube Leakage.
Dabhol	2A	230	12-Jul-10	01.55		Continued.	Tripped due to Electrical Fault
Dabhol	2B	230	12-Jul-10	01.55		Continued.	Tripped due to Electrical Fault
Dabhol	2X	290	12-Jul-10	01.55		Continued.	Tripped due to Electrical Fault
Cent_Sect	TARAPUR-3	540	13-Jul-10	06.19	20-Jul-10	14.03	Reactor Problem.
Koradi	Unit 7	210	17-Jul-10	06.44	19-Jul-10	15.37	Boiler Tube Leakage
Cent_Sect	sipat-5	500	17-Jul-10	21.17	19-Jul-10	03.20	Boiler Tube Leakage
Nasik	Unit 1	120	19-Jul-10	17.01	22-Jul-10	12.55	Boiler Tube Leakage.
Tata	Trombay 7B	60	19-Jul-10	14.23	21-Jul-10	18.24	Boiler Tube Leakage.
Chandrapur	Unit 5	500	19-Jul-10	17.58	20-Jul-10	00:23	Vaccum Problem.
Dabhol	3A	230	20-Jul-10	01.20	20-Jul-10	12.40	Due to Generator Breaker Trouble.
Bhusawal	Unit 2	210	20-Jul-10	19.00	22-Jul-10	15.05	Boiler Tube Leakage

Parli	Unit 7	250	21-Jul-10	13.15	22-Jul-10	15.45	Flame Failure.
Tata	Trombay 5	500	22-Jul-10	14.05	22-Jul-10	19.00	Tripped on MTF,due to air flow less.
Cent_Sect	Tarapur 1	80	22-Jul-10	13.19	26-Jul-10	03.10	Maintenance work.
Chandrapur	Unit 6	500	23-Jul-10	03.24	24-Jul-10	23.13	BLR T/L,
Uran	Unit 5	108	23-Jul-10	00.25	24-Jul-10	01.15	Boiler Inspection.
Nasik	Unit 3	210	23-Jul-10	19.35	25-Jul-10	02.50	E13 Valve leakage
REL	2	250	23-Jul-10	16.04	25-Jul-10	10.56	Boiler Tube Leakage
Chandrapur	Unit 2	210	24-Jul-10	22.43	28-Jul-10	07.47	Reheater tube leakage.
Khaparkheda	Unit 4	210	24-Jul-10	15.56	26-Jul-10	20.23	Boiler tube leakage.
Chandrapur	Unit 6	500	25-Jul-10	07.38	25-Jul-10	18.08	Tripped due to Consor Extraction pump tripped
Paras	Unit 3	250	25-Jul-10	18.00	25-Jul-10	22.01	Tripped on Flame Failure
Nasik	Unit 1	120	26-Jul-10	10.30		Continued.	Boiler Tube Leakage.
Bhusawal	Unit 2	210	27-Jul-10	12.56		Continued.	Boiler Tube Leakage.
Bhusawal	Unit 1	58	28-Jul-10	03.45		Continued.	Trip.
Koradi	Unit 2	105	28-Jul-10	11.31		Continued.	Bunkering Problem.