

GENERATING UNIT OUTAGES FOR THE WEEK

FROM 23-Aug-10 TO 29-Aug-10

UNIT UNDER PLANNED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reason
Cent_Sect	KARPR1	220	1-Jul-08	00:10		Continued.	COH(En-Mass Coolant Clnel Replacement)
Parli	Unit 4	210	5-Jul-10	09:27	24-Aug-10	12:30	Capital Overhaul
Koyna	ST-IV 1	250	16-Jul-10	00:00		Continued.	Preparing Work for 2nd Lake Tapping.
Koyna	ST-IV 2	250	16-Jul-10	00:00		Continued.	Preparing Work for 2nd Lake Tapping.
Koyna	ST - IV 3	250	16-Jul-10	00:00		Continued.	Preparing Work for 2nd Lake Tapping.
Koyna	ST - IV 4	250	16-Jul-10	00:00		Continued.	Preparing Work for 2nd Lake Tapping.
Bhusawal	Unit 3	210	31-Jul-10	05:26		Continued.	Annual Overhaul.
Cent_Sect	KARPR2	220	14-Aug-10	14:16		Continued.	Annual Overhaul.
Cent_Sect	NTPC(V-8)	500	20-Aug-10	00:46		Continued.	AOH.
Khaparkheda	Unit 2	210	27-Aug-10	23:40		Continued.	Capital Overhaul

UNIT UNDER FORCED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reason
Uran	Unit 2	60	4-Oct-08	19:00		Continued.	Gas Restriction
Uran	Unit 4	60	1-Apr-09	00:00		Continued.	Gas Restriction
Uran	Unit 3	60	16-Jun-10	19:52		Continued.	R.M.Work.
Parli	Unit 1	30	18-Jun-10	12:11		Continued.	For Scrapping.
Dabhol	2A	230	12-Jul-10	01:55		Continued.	Tripped due to Electrical Fault
Dabhol	2B	230	12-Jul-10	01:55	24-Aug-10	20:33	Tripped due to Elect.Fault
Dabhol	2X	290	12-Jul-10	01:55	25-Aug-10	10:00	Tripped due to Elect.Fault
Koradi	Unit 4	105	5-Aug-10	10:02	23-Aug-10	09:25	Condensor tube leakage.
Bhusawal	Unit 1	58	10-Aug-10	06:05	23-Aug-10	08:31	Wet Coal
Koradi	Unit 3	105	15-Aug-10	14:26	24-Aug-10	19:44	Tripped due to LT supply fail
Khaparkheda	Unit 4	210	16-Aug-10	02:50	26-Aug-10	08:50	Tripped on Generator side Liquid sealing leakage
Nasik	Unit 1	120	19-Aug-10	01:25	24-Aug-10	10:15	Coal Mill Problem.
Chandrapur	Unit 4	210	19-Aug-10	15:49	27-Aug-10	20:07	Furnace Pressure High
Nasik	Unit 2	120	20-Aug-10	07:50	23-Aug-10	10:45	Steam Temperature high
Paras	Unit 3	250	20-Aug-10	22:17	25-Aug-10	17:59	Coal mill tripped.
Parli	Unit 5	210	21-Aug-10	05:46	23-Aug-10	03:35	Drum level low.
Parli	Unit 6	250	22-Aug-10	11:15	24-Aug-10	21:25	Hydrogen Tube Leakage
Koradi	Unit 6	210	22-Aug-10	10:41	25-Aug-10	00:28	Boiler Tube Leakage
Paras	Unit 2	55	23-Aug-10	04:11	24-Aug-10	20:45	Boiler Tube Leakage
Parli	Unit 7	250	23-Aug-10	16:20	23-Aug-10	19:22	Reheater Protection operated
Parli	Unit 7	250	23-Aug-10	11:29	23-Aug-10	15:36	Transformer Failure
Dabhol	1A	230	23-Aug-10	17:15	23-Aug-10	22:59	Tripped due to Electrical fault
Dabhol	1B	230	23-Aug-10	17:15	23-Aug-10	18:53	Tripped due to Electrical Fault
Dabhol	1X	290	23-Aug-10	17:15	23-Aug-10	20:55	Tripped due to Electrical Fault
Chandrapur	Unit 6	500	24-Aug-10	02:26	25-Aug-10	02:32	Flame Failure
Dabhol	1A	230	24-Aug-10	06:00	24-Aug-10	08:09	Tripped
Dabhol	1B	230	24-Aug-10	06:00	24-Aug-10	14:08	Tripped
Dabhol	1X	290	24-Aug-10	06:00	24-Aug-10	12:14	Tripped
Koradi	Unit 4	105	24-Aug-10	06:02		Continued.	Reverse Power Flow relay operated
Nasik	Unit 1	120	24-Aug-10	11:30	24-Aug-10	14:05	Steam Line Pressure Low
Koradi	Unit 5	200	24-Aug-10	07:16	24-Aug-10	10:05	Furnance Pressure High
Dabhol	3B	230	24-Aug-10	13:02	24-Aug-10	16:56	Tripped on Fire Protection
Chandrapur	Unit 1	210	24-Aug-10	21:45	25-Aug-10	05:06	Tripped due to Thyristor blocked & Failure of AC supply
Koradi	Unit 5	200	25-Aug-10	19:41	26-Aug-10	02:27	Furnace Pressure High.
Koradi	Unit 1	105	25-Aug-10	11:51		Continued.	Boiler Inspection.
Koradi	Unit 6	210	26-Aug-10	02:45	26-Aug-10	14:21	Furnace Pressure High.
Koradi	Unit 7	210	26-Aug-10	02:45	27-Aug-10	16:47	Poor Bunkering.
Koradi	Unit 5	200	26-Aug-10	04:39	26-Aug-10	09:06	Furnace Pressure High.
Nasik	Unit 3	210	27-Aug-10	07:50		Continued.	Boiler tube leakage.
Chandrapur	Unit 6	500	27-Aug-10	13:01	27-Aug-10	16:17	Furnace pressure high.
Paras	Unit 4	250	27-Aug-10	12:16	27-Aug-10	15:06	Loss of fuel.
Bhusawal	Unit 1	58	27-Aug-10	19:40		Continued.	Wet coal problem.
Chandrapur	Unit 4	210	27-Aug-10	21:28	28-Aug-10	18:27	Tripped on Differential Expantion
Koradi	Unit 5	200	28-Aug-10	00:57	30-Aug-10	00:39	Boiler tube leakage.
Chandrapur	Unit 4	210	28-Aug-10	19:43		Continued.	Tripped on Differential Expantion.
Chandrapur	Unit 3	210	28-Aug-10	16:08	28-Aug-10	20:00	Furance Pressure high.
Khaparkheda	Unit 4	210	28-Aug-10	23:18		Continued.	Heavy seal oil leakage of Generator
Parli	Unit 7	250	29-Aug-10	09:15	29-Aug-10	11:42	Boiler fuel supply fail.
Paras	Unit 4	250	29-Aug-10	20:20		Continued.	Flame failure.