

GENERATING UNIT OUTAGES FOR THE WEEK

FROM 20-Sep-10 TO 26-Sep-10

UNIT UNDER PLANNED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reason
Cent_Sect	KARPR1	220	1-Jul-08	00:10		Continued.	COH(En-Mass Coolant Clanel Replacement)
Koyna	ST-IV 1	250	16-Jul-10	00:00		Continued.	Preparing Work for 2nd Lake Tapping.
Koyna	ST-IV 2	250	16-Jul-10	00:00		Continued.	Preparing Work for 2nd Lake Tapping.
Koyna	ST - IV 3	250	16-Jul-10	00:00		Continued.	Preparing Work for 2nd Lake Tapping.
Koyna	ST - IV 4	250	16-Jul-10	00:00		Continued.	Preparing Work for 2nd Lake Tapping.
Cent_Sect	KARPR2	220	14-Aug-10	14:16		Continued.	Annual Overhaul.
Koradi	Unit 4	105	24-Aug-10	06:02		Continued.	Annual Overhaul.
Khaparkheda	Unit 2	210	27-Aug-10	23:40		Continued.	Capital Overhaul
Nasik	Unit 4	210	15-Sep-10	10:55		Continued.	Annual Overhaul.
Cent_Sect	NTPC(V-6)	210	19-Sep-10	13:56		Continued.	Annual overhaul.

UNIT UNDER FORCED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reason
Uran	Unit 2	60	4-Oct-08	19:00		Continued.	Gas Restriction
Uran	Unit 4	60	1-Apr-09	00:00		Continued.	Gas Restriction
Uran	Unit 3	60	16-Jun-10	19:52		Continued.	R.M.Work.
Parli	Unit 1	30	18-Jun-10	12:11		Continued.	For Scrapping.
Dabhol	2A	230	12-Jul-10	01:55		Continued.	Tripped due to Electrical Fault
Bhusawal	Unit 1	58	1-Sep-10	23:30	24-Sep-10	19:00	Wet Coal
Nasik	Unit 2	120	10-Sep-10	01:00		Continued.	Bunkering Problem.
Chandrapur	Unit 3	210	14-Sep-10	23:38	20-Sep-10	08:40	Furnance Pressure High
Parli	Unit 2	30	16-Sep-10	15:20	23-Sep-10	23:12	Furnance Pressure High.
Parli	Unit 3	210	17-Sep-10	05:33	25-Sep-10	22:43	Furnance Pressure High
Parli	Unit 5	210	17-Sep-10	14:07	20-Sep-10	22:48	Furnance Pressure High.
Chandrapur	Unit 2	210	18-Sep-10	00:20	21-Sep-10	22:24	Furnance Pressure High.
Parli	Unit 4	210	18-Sep-10	20:13	20-Sep-10	03:06	High furnance pressure.
CPP	JSW_JAIGAD	300	18-Sep-10	16:00	25-Sep-10	04:39	Planned shutdown.
Koradi	Unit 1	105	19-Sep-10	18:18	25-Sep-10	01:43	Boiler tube leakage.
Bhusawal	Unit 3	210	20-Sep-10	08:37	20-Sep-10	10:21	Furnance Pressure high.
Bhusawal	Unit 3	210	20-Sep-10	14:57	20-Sep-10	16:32	Furnance Pressure high.
Uran	Unit 5	108	21-Sep-10	03:41	21-Sep-10	04:35	Boiler Protection
Parli	Unit 4	210	21-Sep-10	13:07	21-Sep-10	17:37	Flame Failure
Chandrapur	Unit 3	210	21-Sep-10	10:05	21-Sep-10	13:10	Furnance Pressure High
Parli	Unit 5	210	21-Sep-10	14:10	21-Sep-10	18:57	Furnance Pressure High
Parli	Unit 6	250	21-Sep-10	19:40	21-Sep-10	23:29	Flame Failure
Parli	Unit 7	250	21-Sep-10	21:27	21-Sep-10	23:24	Main Steam Temp.Low
Koradi	Unit 6	210	21-Sep-10	20:08	21-Sep-10	22:11	Coal Mill Trip
Chandrapur	Unit 2	210	22-Sep-10	00:03	22-Sep-10	20:17	IPT Diff.Expansion
Chandrapur	Unit 4	210	22-Sep-10	01:27		Continued.	Boiler Tube Leakage
Nasik	Unit 5	210	22-Sep-10	12:15	22-Sep-10	14:05	Tripped due to ID fan problem.
Koradi	Unit 6	210	23-Sep-10	02:10	23-Sep-10	03:15	Furnance Pressure High.
Nasik	Unit 1	120	23-Sep-10	10:25	26-Sep-10	03:25	BLR T/L.
Nasik	Unit 3	210	23-Sep-10	09:35	23-Sep-10	12:15	Furnance Pressure Low.
Khaparkheda	Unit 1	210	23-Sep-10	13:23	23-Sep-10	16:15	Furnance Pressure High.
Koradi	Unit 2	105	23-Sep-10	10:32		Continued.	Bunkering Problem.
Koradi	Unit 7	210	24-Sep-10	03:11	24-Sep-10	20:22	Furnance Pressure High.
Bhusawal	Unit 3	210	24-Sep-10	03:49	26-Sep-10	11:35	BLR T/L.
Parli	Unit 7	250	24-Sep-10	13:47	24-Sep-10	17:12	Generator protection operated.
Dabhol	1A	230	24-Sep-10	16:33	24-Sep-10	21:48	Gas Turbine Power supply problem.
CPP	JSW_JAIGAD	300	25-Sep-10	19:38	26-Sep-10	02:00	Steam line leakage.
Khaparkheda	Unit 1	210	25-Sep-10	15:33	25-Sep-10	17:24	Air compressor Trip.
Bhusawal	Unit 2	210	25-Sep-10	07:25		Continued.	Boiler tube leakage.
Chandrapur	Unit 3	210	26-Sep-10	05:49	26-Sep-10	09:25	Furnance pressure high.
Parli	Unit 2	30	26-Sep-10	07:35		Continued.	Flame failure.