

GENERATING UNIT OUTAGES FOR THE WEEK

FROM 27-Sep-10 TO 3-Oct-10

UNIT UNDER PLANNED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reason
Cent_Sect	KARPR1	220	1-Jul-08	00:10		Continued.	COH(En-Mass Coolant Clanel Replacement)
Koyna	ST-IV 1	250	16-Jul-10	00.00		Continued.	Preparing Work for 2nd Lake Tapping.
Koyna	ST-IV 2	250	16-Jul-10	00.00		Continued.	Preparing Work for 2nd Lake Tapping.
Koyna	ST - IV 3	250	16-Jul-10	00.00		Continued.	Preparing Work for 2nd Lake Tapping.
Koyna	ST - IV 4	250	16-Jul-10	00.00		Continued.	Preparing Work for 2nd Lake Tapping.
Cent_Sect	KARPR2	220	14-Aug-10	14:16	30-Sep-10	21.45	Annual Overhaul.
Koradi	Unit 4	105	24-Aug-10	06.02		Continued.	Annual Overhaul.
Khaparkheda	Unit 2	210	27-Aug-10	23.40		Continued.	Capital Overhaul
Nasik	Unit 4	210	15-Sep-10	10.55		Continued.	Annual Overhaul.
Cent_Sect	NTPC(V-6)	210	19-Sep-10	13.56		Continued.	Annual overhaul.
Cent_Sect	TARAPUR-3	540	3-Oct-10	22.03		Continued.	Steam line work.
Cent_Sect	sipat-5	500	4-Oct-10	01.58		Continued.	Boiler revalidation.

UNIT UNDER FORCED OUTAGE

name	unit_no	derat_cap	date_trip	time_trip	date_sync	time_sync	reason
Uran	Unit 2	60	4-Oct-08	19.00		Continued.	Gas Restriction
Uran	Unit 4	60	1-Apr-09	00:00		Continued.	Gas Restriction
Uran	Unit 3	60	16-Jun-10	19.52		Continued.	R.M.Work.
Parli	Unit 1	30	18-Jun-10	12:11		Continued.	For Scrapping.
Dabhol	2A	230	12-Jul-10	01.55		Continued.	Tripped due to Electrical Fault
Nasik	Unit 2	120	10-Sep-10	01.00		Continued.	Bunkering Problem.
Chandrapur	Unit 4	210	22-Sep-10	01.27	27-Sep-10	11.51	Boiler Tube Leakage
Koradi	Unit 2	105	23-Sep-10	10.32	2-Oct-10	08.09	Bunkering Problem.
Bhusawal	Unit 2	210	25-Sep-10	07.25	29-Sep-10	09.01	Boiler tube leakage.
Parli	Unit 2	30	26-Sep-10	07.35	27-Sep-10	13.17	Flame failure.
Khaparkheda	Unit 3	210	27-Sep-10	00.20	27-Sep-10	04.29	Drum level low.
Koradi	Unit 5	200	27-Sep-10	19.35	28-Sep-10	04.40	Flame Failure
Khaparkheda	Unit 3	210	27-Sep-10	17.51	27-Sep-10	22.08	Drum Level High
Koradi	Unit 3	105	28-Sep-10	03.38	28-Sep-10	07.10	Low Coal Flow
Koradi	Unit 6	210	29-Sep-10	18.41		Continued.	Air Reheater Tripped.
Chandrapur	Unit 5	500	30-Sep-10	03.36	3-Oct-10	11.17	Suspected Tube Leakage.
CPP	JSW_JAIGAD	300	30-Sep-10	11.10	30-Sep-10	21.04	Trip.
Chandrapur	Unit 1	210	30-Sep-10	08.46	3-Oct-10	15.30	Furnace Pressure High.
Cent_Sect	NTPC(K-3)	210	30-Sep-10	13.18	2-Oct-10	02.10	Boiler Tube Leakage.
Paras	Unit 2	55	1-Oct-10	12.10	1-Oct-10	13.10	C.B.Problem
Koradi	Unit 1	105	2-Oct-10	13.38		Continued.	Boiler tube leakage.
Khaparkheda	Unit 4	210	2-Oct-10	14.26	3-Oct-10	17.16	Boiler tube leakage.